

Headquarters Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	HHT/7/17 Cav
OH58	6816841	85	940	142	1082	87	1169	40	1209	40	1249	58	1307	
OH58	6816928	123	586	14	600	92	692	0	692	5	697	34	731	Accident 710923; See CW2 Barklage
OH58	Total	208		156		179		40		45		92		
UH1H	6616030	11	2453	44	2497	50	2547	32	2579	17	2596	39	2635	
UH1H	6719492	36	2132	50	2182	10	2192	46	2238	34	2272	13	2285	
UH1H	6915507	42	679	29	708	42	750	34	784	37	821	27	848	
UH1H	Total	89		123		102		112		88		79		
Troop	Totals	297		279		281		152		133		171		

This data comes from the VHPA's copy of the Army Goldbook database that contains a monthly report by aircraft of hours flown, accumulative hours on the airframe, and the unit. Data from the VHPA's Helicopter database that contains details from accident reports, battle damage reports (including crew injuries) plus aircraft disposition (repaired or removed from inventory). The 'From' unit identifies the previous unit prior to being assigned to this 7/17th Cav unit. The 'To' unit identified the unit who received the aircraft from this 7/17th Cav unit. The 79th Transportation Company (Aircraft Direct Support) was located at Qui Nhon. The 388th Transportation Company (Aircraft Direct Support) was located at Vung Tau. The 604th Transportation Company (Aircraft Direct Support) was located at Pleiku. LTI means Lost To Inventory. The Army used this term to mean the aircraft was destroyed and therefore removed from inventory.

A Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS A/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
AH1G	6615292	16	1400	39	1439	29	1468	11	1479	24	1503	15	1518	
AH1G	6715603	0	1636	33	1669	40	1709	17	1726	8	1734	0	1734	
AH1G	6715607	21	1667	11	1678	31	1709	17	1726	22	1748	22	1770	
AH1G	6715619	3	1465	74	1539	17	1556	30	1586	46	1632	19	1651	From F/4 CAV
AH1G	6715715	19	1169	53	1222	20	1242	26	1268	33	1301	0	1301	
AH1G	6715747	29	1350	73	1423	7	1430	35	1465	46	1511	19	1530	
AH1G	6815076	35	1176	49	1225	8	1233	25	1258	35	1293	34	1327	
AH1G	6815195	44	1096	28	1124	41	1165	52	1217	11	1228	21	1249	
AH1G	6817026	18	1284	45	1329	33	1362	45	1407	13	1420	20	1440	
AH1G	Total	185		405		226		258		238		150		

A Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS A/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
OH6A	6512994	32	1255	72	1327	48	1375	64	1439	26	1465	53	1518	
OH6A	6607916	25	330	19	349	24	373	34	407	30	437	64	501	From 605 TC DS
OH6A	6614391	27	2361	12	2373	35	2408	49	2457	30	2487	10	2497	From CONUS repairs
OH6A	6617811	47	1879	26	1905	1	1906	12	1918	31	1949	33	1982	
OH6A	6716114	12	1695	56	1751	70	1821	18	1839	27	1866	36	1902	
OH6A	6716121							18	2406	31	2437	29	2466	From Hughes repairs
OH6A	6716304	19	978	35	1013	33	1046	41	1087	25	1112	13	1125	
OH6A	6817246	27	1014	29	1043	8	1051	2	1053	0	1053	1	1054	SP4 Reynolds
OH6A	6817317	7	1308	41	1349	25	1374	5	1379	5	1384	30	1414	Accident 711005; See WO1 Shupe &
OH6A	6817345	42	828	23	851	32	883	17	900	47	947	14	961	
OH6A	6916044	23	370	48	418	19	437	32	469	57	526	21	547	
OH6A	Total	261		361		295		292		309		304		

A Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS A/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
UH1H	6616574	27	1361	32	1393	47	1440	60	1500	36	1536	1	1537	
UH1H	6717338	18	2488	35	2523	51	2574	48	2622	15	2637	13	2650	
UH1H	6717752	43	2022	26	2048	13	2061	52	2113	31	2144	13	2157	
UH1H	6815368	37	1479	20	1499	30	1529	24	1553	44	1597	8	1605	
UH1H	6815689	18	1199	11	1210	61	1271	20	1291	3	1294	6	1300	Lost about 71/12 reason unknown
UH1H	6816136	14	1761	19	1780	37	1817	28	1845	27	1872	31	1903	
UH1H	6915289	37	835	68	903	47	950	25	925	79	1004	0	1004	To 608 TC DS reason unknown
UH1H	6915385	To HHC 12 CAG in 7107 in flyable condition reason unknown												
UH1H	Total	194		211		286		257		235		72		
Troop	Totals	640		977		807		807		782		526		

This data comes from the VHPA's copy of the Army Goldbook database that contains a monthly report by aircraft of hours flown, accumulative hours on the airframe, and the unit. Data from the VHPA's Helicopter database that contains details from accident reports, battle damage reports (including crew injuries) plus aircraft disposition (repaired or removed from inventory). The 'From' unit identifies the previous unit prior to being assigned to this 7/17th Cav unit. The 'To' unit identified the unit who received the aircraft from this 7/17th Cav unit. The 79th Transportation Company (Aircraft Direct Support) was located at Qui Nhon. The 388th Transportation Company (Aircraft Direct Support) was located at Vung Tau. The 604th Transportation Company (Aircraft Direct Support) was located at Pleiku. LTI means Lost To Inventory. The Army used this term to mean the aircraft was destroyed and therefore removed from inventory.

After a careful review of all aircraft assigned to A Troop during this six month period in both the Goldbook and Helicopter databases it seems clear that while A Troop logged many hours there are virtually zero battle damage records for this period. During the same period, both B and C Troops have many such records. This leads one to suspect either lost records or that they were never generated by the maintenance personnel.

B Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS B/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
AH1G	6715491	3	1792	59	1851	33	1884	44	1928	93	2021	33	2054	
AH1G	6715626	2	2074	14	2088	70	2158	12	2170	0	2170	37	2207	Accident 710801; See CPTs Welsh & Hess
AH1G	6715629	34	1913	11	1924	47	1971	22	1993	29	2022	0	2022	
AH1G	6715675	34	1054	14	1068	117	1185	91	1276	59	1335	53	1388	
AH1G	6817020	39	1091	43	1134	66	1200	98	1298	41	1339	43	1382	
AH1G	6817036	9	1305	12	1317	18	1335	87	1422	66	1488	31	1519	
AH1G	6817043	30	664	40	704	40	744	0	744	42	786	24	810	
AH1G	6817084	15	720	18	738	75	813	50	863	28	891	37	928	From 57 AHC
AH1G	6817113	37	1015	31	1046	16	1062	68	1130	39	1169	33	1202	
AH1G	Total	203		242		482		472		397		291		

B Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS B/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
OH6A	6512998	0	1830	43	1873	52	1925	24	1949	40	1989	30	2019	
OH6A	6607782	24	1430	LTI on 710811; See WO1 Logan SSG Wheeler										
OH6A	6607842	43	1619	31	1650	31	1681	53	1734	0	1734	From 5 Avn Det; LTI on 711127; details please		
OH6A	6607938	22	1677	16	1693	26	1719	60	1779	0	1779	LTI on 711128; details please		
OH6A	6617828							46	1293	59	1352	32	1384	From Hughes repairs
OH6A	6617833			From CONUS repairs				55	2264	0	2264	LTI on 711128; See CPT Hartley		
OH6A	6716084							57	2357	51	2408	41	2449	From Hughes repairs
OH6A	6716119	9	2090	6	2096	10	2106	29	2135	10	2145	35	2180	
OH6A	6716240	49	1090	46	1136	Accident & LTI on 710828; See WO1 Bucklew & SGT Cooksey								
OH6A	6716373	21	1573	53	1626	70	1696	LTI on 711005; need details						
OH6A	6716386	28	948	28	976	51	1027	46	1073	19	1092	14	1106	LTI on 711227; need details
OH6A	6716491											20	1545	From 166 TC CO (CONUS repairs)
OH6A	6817200									35	1374	14	1388	From Hughes repairs
OH6A	6817217	4	1749	17	1766	37	1803	21	1824	42	1866	9	1875	
OH6A	6817233	11	1870	8	1878	60	1938	76	2014	From C/1/9 Cav; LTI on 711101; need details				
OH6A	Total	211		248		337		467		256		195		

B Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS B/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
UH1H	6601108	32	2712	7	2719	44	2763	43	2806	27	2833	23	2856	
UH1H	6616175	33	1618	38	1656	33	1689	49	1738	74	1812	36	1848	
UH1H	6616469	18	2507	40	2547	51	2598	60	2658	50	2708	0	2708	
UH1H	6717849	17	1770	34	1804	58	1862	47	1909	51	1960	13	1973	
UH1H	6915384	18	993	65	1058	72	1130	87	1217	50	1267	83	1350	
UH1H	6915665	35	628	44	672	79	751	67	818	101	919	2	921	
UH1H	7015760	35	94	44	138	36	174	59	233	22	255	Dropped from Army Inventory Dec 71; need details		
UH1H	7015762	24	119	36	155	32	187	76	263	11	274	Dropped from Army Inventory Dec 71; need details		
UH1H	Total	212		308		405		488		386		157		
Troop	Totals	626		798		1224		1427		1039		643		

This data comes from the VHPA's copy of the Army Goldbook database that contains a monthly report by aircraft of hours flown, accumulative hours on the airframe, and the unit. Data from the VHPA's Helicopter database that contains details from accident reports, battle damage reports (including crew injuries) plus aircraft disposition (repaired or removed from inventory). The 'From' unit identifies the previous unit prior to being assigned to this 7/17th Cav unit. The 'To' unit identified the unit who received the aircraft from this 7/17th Cav unit. The 79th Transportation Company (Aircraft Direct Support) was located at Qui Nhon. The 388th Transportation Company (Aircraft Direct Support) was located at Vung Tau. The 604th Transportation Company (Aircraft Direct Support) was located at Pleiku. LTI means Lost To Inventory. The Army used this term to mean the aircraft was destroyed and therefore removed from inventory.

C Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	C/7/17 Cav
AH1G	6715627	37	1569	80	1649	29	1678	90	1768	25	1793	66	1859	
AH1G	6715822	55	1220	42	1262	66	1328	38	1366	35	1401	8	1409	
AH1G	6815047	47	1395	44	1439	20	1459	26	1485	13	1498	17	1515	
AH1G	6815101	46	1142	72	1214	44	1258	0	1258	16	1274	53	1327	
AH1G	6815103	25	1338	50	1388	95	1483	22	1505	67	1572	22	1594	
AH1G	6815144	64	1401	41	1442	73	1515	38	1553	25	1578	45	1623	
AH1G	6817076	50	991	49	1040	52	1092	7	1099	60	1159	37	1196	
AH1G	6817081	41	959	46	1005	14	1019	25	1044	2	1046	36	1082	
AH1G	6817088	28	632	24	656	29	685	57	742	41	783	5	788	
AH1G	Total	393		448		422		303		284		289		

C Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS C/7/17 Cav	
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112		
OH6A	6716027	60	1487	80	1567	LTI on 710904; See Devaux & Snead									
OH6A	6716083	15	1801	55	1856	30	1886	0	1886	0	1886	0	1886	Need details for zero time last three months	
OH6A	6716089			From CONUS repairs				55	2209	9	2218	21	2239	Accident 711111; See Middendorf & Jackson	
OH6A	6716113	49	1372	51	1423	40	1463	24	1487	11	1498	5	1503	Warstory on 710815; See WO1 Purser	
OH6A	6716117	51	1330	49	1379	31	1410	79	1489	36	1525	31	1556		
OH6A	6716157	70	117	17	134	To ARADMAC for CONUS repairs in 7109; need details									
OH6A	6716286	82	504	88	592	59	651	31	682	0	682	30	712	From Hughes factory repairs	
OH6A	6716326							65	2462	24	2486	37	2523	From CONUS repairs	
OH6A	6716579	16	841	65	906	69	975	24	999	20	1019	26	1045		
OH6A	6817141	29	872	51	923	41	964	LTI on 710920; Need details							
OH6A	6817327	52	1550	13	1563	47	1610	43	1653	15	1668	37	1705		
OH6A	6915988							80	562	42	604	28	632	From CONUS repairs	
OH6A	Total	424		469		317		401		157		215			

C Troop Aircraft Data for the period July through December 1971

MODEL	TAIL NUMBER	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	HOURS FLOWN	AIR FRAME	COMMENTS C/7/17 Cav
		7107	7107	7108	7108	7109	7109	7110	7110	7111	7111	7112	7112	
UH1H	6616258	60	2581	76	2657	74	2731	76	2807	5	2812	4	2816	
UH1H	6717267	57	2210	60	2270	49	2319	64	2383	57	2440	73	2513	
UH1H	6717290	74	2137	27	2164	81	2245	53	2298	45	2343	38	2381	
UH1H	6719489	39	2344	70	2414	35	2449	52	2501	47	2548	37	2585	
UH1H	6816555	35	861	77	938	50	988	42	1030	24	1054	0	1054	From HHC 17 CAG
UH1H	6816588	46	1225	74	1299	65	1364	45	1409	44	1453	36	1489	
UH1H	6915398	38	1022	62	1084	78	1162	22	1184	77	1261	6	1267	
UH1H	7015782	77	174	77	251	77	328	99	427	2	429	Dropped from Army Inventory Dec 71; need details		
UH1H	Total	426		523		509		453		301		194		
Troop	Totals	1243		1440		1248		1157		742		698		

This data comes from the VHPA's copy of the Army Goldbook database that contains a monthly report by aircraft of hours flown, accumulative hours on the airframe, and the unit. Data from the VHPA's Helicopter database that contains details from accident reports, battle damage reports (including crew injuries) plus aircraft disposition (repaired or removed from inventory). The 'From' unit identifies the previous unit prior to being assigned to this 7/17th Cav unit. The 'To' unit identified the unit who received the aircraft from this 7/17th Cav unit. The 79th Transportation Company (Aircraft Direct Support) was located at Qui Nhon. The 388th Transportation Company (Aircraft Direct Support) was located at Vung Tau. The 604th Transportation Company (Aircraft Direct Support) was located at Pleiku. LTI means Lost To Inventory. The Army used this term to mean the aircraft was destroyed and therefore removed from inventory.